

RECEIVED

AUG 2 3 2002

TECH CENTER 1600/2900

09 624855



FIG.1B



FIG.2A






FIG.2B





6673604

3/7

FIG.3








FIG.4

Diastolic Pressure-Volume











AUG 2 3 2002 TECH CENTER 1600/2900

6/7



FIG.7A





FIG.7B



RECEIVED

AUG 2 3 2002 TECH CENTER 1600/2900

7/7

ME 16 200 9 347

Decreased Ventricular Remodeling




FIG.8B

